## SRB CRITICAL ITEMS LIST

SUBSYSTEM: ELECTRICAL AND INSTRUMENTATION

ITEM NAME: SRB OF Watertight Reusable Cable X13W1R P1/P2 and X13W5R P1/P2 (Pneumatic

Pressurization System)

FART NO.: 10400-0017 FM CODE: A02A

10400-0021

ITEM CODE: 50-04-X13 REVISION: Basic

CRITICALITY CATEGORY: 1R REACTION TIME: Immediate

NO. REQUIRED: 1 each DATE: March 1, 1995

CRITICAL PHASES: Boost SUPERCEDES: March 1, 1994

FMEA PAGE NO.: D-659A ANALYST: R. Smith/ A. Craft

SHEET 1 OF 2 APPROVED: P. Kalia

FAILURE MODE AND CAUSES: Loss of input power to Pnenmatic Pressurization System in both cables due to:

 One pin or wire short to ground caused by: bent pin, contamination in connector, insulation breakdown, frayed shielding, abraded or cut insulation.

FAILURE EFFECT SUMMARY: Loss of ORB Bos A and Bus B Power results in loss of Thrust Vector Control and Separation capability, leading to loss of mission, vehicle and crew. One success path remains after the first failure. Operation is not affected until both paths are lost.

## REDUNDANCY SCREENS AND MEASUREMENTS:

- Pass All cables are system tested during ground turnaround sequence.
- Pass Voltage measurements B76V1600C and B76V1601C.
- Pass No credible causes.

50 - 213 DR Document: RA-21

FM Code: 50-04-X13-A02A Date, March I, 1995 RATIONALE FOR RETENTION: A. DESIGN Per Appendix A Section # II B. TESTING 1) VENDOR RELATED Per Appendix B Section # [A 2) KSC RELATED Per Appendix B Section # 11B SYSTEM/ UNIQUE FUNCTIONAL. Cables are tested during ET/SRB strut electrical mate per OMRSD File V, Vol. I B75BUO.010 (Power Bus A & B isolation test) (Short) Cables are again tested during STT per OMRSD File II, Vol. I, SOOOOO,470. (Power Bus A & B transfer ventication (Short). Last time cables are checked is during Final countdown per File II, Vol. I SOOFRO,070 .(APU startup) (Short). C. INSPECTION VENDOR RELATED Per Appendix C Section # I 2) KSC RELATED Per Appendix C Section # [78] D. FAILURE HISTORY Failure Histories may be obtained from the PRACA database.

E. OPERATIONAL USE

Not applicable to this failure mode.

Supercedes: March 1, 1994 DR Document: RA-21